

California Regional Water Quality Control Board North Coast Region

William R. Massey, Chairman

http://www.swrcb.ca.gov/rwqcb1/

5550 Skylane Boulevard, Suite A, Santa Rosa, California 95403 Phone 1-877-721-9203 Office (707) 576-2220 FAX (707) 523-0135



November 17, 2004

Ms. Julie B. Raming Georgia-Pacific Corporation P.O. Box 105605 Atlanta, GA 30348-5605

Dear Ms. Raming:

Subject: Response to Comments

File: Georgia-Pacific Fort Bragg Sawmill, 90 West Redwood Avenue, Fort Bragg

Case No. 1NMC462

Thank you for the September 9, 2004 response from TRC to my August 12, 2004 comment letter. I have the following comments to the response:

- It was stated in the response that a workplan would be submitted for additional investigation. I have not yet received that workplan. Please submit the workplan for the additional assessments mentioned in the response.
- In response to my comment regarding addressing the possible presence of dioxins, a report from a company called Exponent was included in the response. Five potential sources of dioxins were identified. However, the possible burning of PCB oil waste was not included. In addition, the identified potential source of open burning did not appear to be further addressed. Overall, it is not clear to me if additional sampling is being proposed. Please respond either in the workplan or in a separate letter.
- Regarding the former use of pentachlorophenol or tetrachlorophenol wood treatment chemicals, the number of samples analyzed for SVOCs was cited in the response.
 Please submit a map of the locations that had samples analyzed for the wood treatment chemicals.
- In my August 12, 2004 letter I had recommended an investigation of the extent of waste material and contamination found in pothole P8-T2. One additional pothole was completed in that area. Additional investigation of the extent is needed. The workplan

California Environmental Protection Agency

for additional investigation should include a proposal for additional investigation in this area.

• Regarding the Parcel 8 clinker piles area, the soil under the clinker material should also be investigated. This should be included in the workplan for additional assessment. Also, what is the planned disposition of the clinker material?

Please submit the workplan and any additional responses within two months of the date of this letter. If you have any questions or comments, you may contact me at CHunt@waterboards.ca.gov or (707) 570-3767.

Sincerely,

/ORIGINAL SIGNED BY CHARLES T. VATH FOR/

Craig Hunt

Water Resource Control Engineer

111704_CSH_GP-FB0411letter

cc: Mr. Mohammad R. Bazargani, TRC, 1590 Solano Way, Suite A, Concord, CA 94520-5317

Mr. Doug Heitmeyer, Georgia-Pacific Corporation, 90 West Redwood Avenue, Fort Bragg, CA 95437

Mendocino County Health Department, 501 Low Gap Road, Room 1326, Ukiah, CA 95482

Ms. Linda Ruffing, Community Development Department, City of Fort Bragg, 416 N. Franklin Street, Fort Bragg, CA 95437

Mr. Dave Goble, Public Works Department, 416 N. Franklin Street, Fort Bragg, CA 95437

Mr. Andy Whiteman, City Manager, 416 N. Franklin Street, Fort Bragg, CA 95437

Ms. Loie Rosenkrantz, 17201 Franklin Road, Fort Bragg, CA 95437

Mr. David L. Berry, Department of Toxic Substances Control, P.O. Box 806, Sacramento, CA 95812

Ms. Ashle Crocker, Remy, Thomas, Moose, and Manley, 455 Capitol Mall, Suite 210, Sacramento, CA 95814

Email cc List